

## Under Review Notification

**Raised By:** Michelle Gagnon-Donovan

**Product #:** D117-1028

**Date:** 19.02.22

**Product Name:** Bearpaw Installation

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
D117-1028-011	IIN-D117-1028 Rev B	Y	Y	N	Y	N	Y	Y	19-605	CHG 002
D117-1028-013	IIN-D117-1028 Rev B	Y	Y	N	Y	N	Y	Y	19-605	CHG 001
D117-1028-041	IIN-D117-1028 Rev B	Y	Y	N	Y	N	Y	Y	19-605	CHG 001

**Description of Issue:**

Compatibility needs to be verified with customer before sale of parts.  
D117-1028-011/-013 are not compatible with hoist guard and Schwayder wearplates.

Design Change required.

- |   |  |   |   |
|---|--|---|---|
| <b>Distribution:</b><br><br>VP Operations<br>Director of Operations<br>Director Quality Assurance<br>QC Coordinator | Director of Engineering<br>Chief Engineer<br>Engineering Project Managers<br>Engineering Clerk | Customer Support Manager<br>Production Engineers<br>Production Planners<br>Purchasing Manager | Technical Support<br>Product Manager - Solutions Provider<br>Supply Chain Director / Senior Buyer<br>Marketing Eugene |
|---|--|---|---|